

Safety Issue Type: Recalls

January 13 2021 NHTSA Campaign Number: 21V007000

Tire Tread Separation/Blowout

Tread separation and/or blow-outs while driving may result in a loss of vehicle control, increasing the risk of a crash.

NHTSA Campaign Number 21V007000

Manufacturer Daimler Trucks North America, LLC

Components TIRES

Potential Number of Units Affected 4341

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2020-2022 Freightliner Cascadia sleeper trucks equipped with Bridgestone R284, R268, or R283S ECOPIA steer axle tires in conjunction with a specific air dam. The steer tires may experience tread separation or blow-outs while driving.

Remedy

DTNA will notify owners, and dealers will replace the steer tires, free of charge. The recall is expected to begin March 13, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL872.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Affected Products (3)

Vehicle

MAKE	MODEL	YEAR
FREIGHTLINER	CASCADIA	2020-2022

Associated Documents (6)

Miscellaneous Document- Defect Information Report

RMISC-21V007-1581.pdf 605.817KB

<https://static.nhtsa.gov/odi/rcl/2021/RMISC-21V007-1581.pdf>

Recall Acknowledgement

RCAK-21V007-8813.pdf 244.571KB

<https://static.nhtsa.gov/odi/rcl/2021/RCAK-21V007-8813.pdf>

Defect Notice 573 Report

RCLRPT-21V007-7635.PDF 214.563KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21V007-7635.PDF>

Miscellaneous Document- Defect Information Report

RMISC-21V007-3129.pdf 605.269KB

<https://static.nhtsa.gov/odi/rcl/2021/RMISC-21V007-3129.pdf>

Miscellaneous Document- Frequently Asked Questions

RMISC-21V007-8862.pdf 569.356KB

<https://static.nhtsa.gov/odi/rcl/2021/RMISC-21V007-8862.pdf>

Recall 573 Report- Amendment 1

RCLRPT-21V007-8411.PDF 214.546KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21V007-8411.PDF>