

Safety Issue Type: Recalls

July 02 2021 NHTSA Campaign Number: 21V507000

High Pressure Fuel Rail Assembly May Leak Fuel

A fuel leak in the presence of an ignition source increases the risk of a fire.

NHTSA Campaign Number 21V507000

Manufacturer Marion Body Works Inc.

Components FUEL SYSTEM, DIESEL

Potential Number of Units Affected 52

Summary

Marion Body Works Inc. is recalling certain 2017-2020 Spartan Gladiator and MetroStar vehicles. The sealing washer may not seat correctly in the pilot boreholes, allowing the high-pressure fuel rail assembly to leak.

Remedy

Dealers will inspect the rail threads and fuel lines, and replace the rail as necessary, free of charge. Owner notification letters are expected to be mailed in July 2021. Owners may contact Marion Body Works' customer service at 1-715-754-5261. Marion Body Works' number for this recall is 21V-032.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (8)

Vehicle

MAKE	MODEL	YEAR
SPARTAN FIRE	GLADIATOR	2017-2020
SPARTAN FIRE	METROSTAR	2017-2020

Associated Documents (2)

Recall Acknowledgement

RCAK-21V507-8356.pdf 646.278KB

<https://static.nhtsa.gov/odi/rcl/2021/RCAK-21V507-8356.pdf>

Defect Notice 573 Report

RCLRPT-21V507-7093.PDF 215.195KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21V507-7093.PDF>