

Safety Issue Type: Recalls

July 13 2021 NHTSA Campaign Number: 21V528000

Rear LED Lights Too Bright/FMVSS 108

The excessive brightness may affect the vision of other drivers, increasing the risk of a crash.

NHTSA Campaign Number 21V528000

Manufacturer Summit Bodyworks

Components EXTERIOR LIGHTING

Potential Number of Units Affected 1

Summary

Summit Bodyworks is recalling one 2017 Freightliner M2-106 vehicle. The all-in-one rear LED lights may be too bright, exceeding the maximum light output allowed which may adversely affect the vision of drivers. As such, this vehicle fails to comply with the requirements of the Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Summit Bodyworks will notify the owner, and provide instructions on how to obtain a filter kit from the light manufacturer, free of charge. The owner notification letter is expected to be mailed in July 2021. Owners may contact Summit Bodyworks' customer service at 1-303-348-2681.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (1)

Vehicle

MAKE	MODEL	YEAR
FREIGHTLINER	M2	2017

Associated Documents (3)

Noncompliance Notice 573 Report

RCLRPT-21V528-1651.PDF 214.618KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21V528-1651.PDF>

Recall Acknowledgement

RCAK-21V528-1329.pdf 645.718KB

<https://static.nhtsa.gov/odi/rcl/2021/RCAK-21V528-1329.pdf>

Miscellaneous Document- Recall Return Card

RMISC-21V528-0358.pdf 52.995KB

<https://static.nhtsa.gov/odi/rcl/2021/RMISC-21V528-0358.pdf>